

Vehicle Diagnostic Report

The Report is created by **LAUNCH X-431**

Vehicle Information



Year:2004.09
Make:BMW
Model:316i
VIN:WBAEY31020KS48041
Odometer:221837 km
Vehicle Software Version:V51.66
Diagnostic Application Version:V8.00.037
Diagnostic path:Health Report

Repair Shop

Shop Name:
Address:
Zip Code:
Telephone:
Email:
SN:987940059993
Test Time:2026-05-03 16:30:12



System fault code 【Pre-Repair】

The following systems is abnormal:

SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)

DTC (2)

1.70 MRS: Seat Occupancy Detector

2.02 MRS: Belt Tensioner, Driver

ZKE (Central Body Electronic)

DTC (4)

1.3D GM: Drive For Rear-Lid Unlocking

2.33 GM: Wipers: Interlock Active

3.01 GM: Fuse For Interior Lights, Washer Pump

4.02 GM: Fuse For Central Locking

A/C (Air Conditioning - IHKA)

DTC (1)

1.20 IHKA: AUC Heating

SZM/BZM (Switching/Control Center, Center Console)

DTC (1)

1.0002 SZM: Seat Heating, Left, Short Or Open Circuit

LSZ/LCM (Light Switching Center)

DTC (2)

1.16 LSZ2: Wire / Switch, Turn Indic., Sh. Circ. To Earth

2.17 LSZ2: Wire/Switch, Main B./Headl.Fl., Sh. Circ. To Earth

The following systems are OK:

- 1.EWS (Elec. Immobilize System)
- 2.IC (Instrument Cluster - INSTR)
- 3.RAD (Radio)
- 4.NAV (Navigation System)
- 5.BM (On-Board Monitor)
- 6.SHD (Sliding/Tilting Sunroof)

Disclaimer

This test report is for reference only for vehicle test and maintenance. The vehicle operating data provided in this report are all static data. The detailed dynamic diagnostic data can be read by professional maintenance device, and LAUNCH will not be liable for any accidents and failures arising therefrom!